Monday, 14/01/7308 10:12:22 AM User Linda Lacelle **Process Sheet** Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** : WEARPAD Job Number : 36714 - 2 **Estimate Number** : 12712 P.O. Number Part Number : D35371 This Issue : 14/01/2008 S.O. No. : **Drawing Number** : D3537 REV C Prsht Rev. : NC : N/A Project Number First Issue : 11 Type : SMALL /MED FAB **Drawing Revision** : C Previous Run : 36426 Material Written By : 25/01/2008 **Due Date** Qty: Each Checked & Approved By Comment : Est Rev: A New Issue 07-02-14 JLM Additional Product Job Number: Seq. #: Machine Or Operation: Description: 1.0 M304S16GA 304/316 .063 Sheet Comment: Qty.: 0.1113 sf(s)/Unit Total: 11.1300 sf(s) M304S16GA .063" 304 SS SHEET Batch: 106653 2.0 WATER JET Comment: FLOW WATER JET 1-Cut as per Dwg D3537 B 8-1-15 Dwg Rev: Prog Rev: 2-Deburr if necessary QC2 INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE 4.0 QC8 SECOND CHECK Comment: SECOND CHECK 5.0 BRAKE NC NC BRAKE Comment: NC BRAKE 1-Form as per Dwg D3537 on CNC brake using Jigs DT 8261 and DT 8326.

Page 1


2-Identify as D3537-1

Form: rorocess

			•

monday, 1 #/01/2008 10:12:22 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: WEARPAD Job Number: 36714 Part Number: D35371 Job Number: Seq. #: Machine Or Operation: Description: 6.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 Qty Description A/R 2059B Hardcoat H106834 1-Weld as per Dwg D3537 using Jig DT 8210 2-Remove any weld that penetrated through Wearpadif necessary 7.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 8.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 9.0 POWDER COATING 106442 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref. 4.3.5.6) as per QSI 005 4.3 10.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 11.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: FP-26 12.0 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion

			1
			-
			-
			×
		the second secon	





DART AEROSPACE LTD					Work Order:	36714	
Description: WEAR PAD Inspection Dwg: D3C37-1 Rev: C					Part Number:	D3537-1	
						Page 1 of 1	
FIRST ARTICLE INSPECTION CHECKLIST X First Article Prototype							
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments	
220	4- 00	.332	×				
380	7- ,010	381	>				
1.965	4 .010	1.960	×			5)	
2.795	7- ,010		*		,		
3,500	4010	3500	1			13	
	7- 010	3,621	×				
4.350	4010	4.780	los los		20	E N	
	10 ¹⁷ 10				* 2		
		-					
					¥.		
			-				
					4		
			4			*	

Reasured by:	Audited by:	Prototype Approval:	1
Date: 8-	-15 Date: Folox/16		1/2
Rev Date Cha	nge		
*	Issue	Revised by KJ/JLM	Approved

